



C-AD ACTIVITY FEBRUARY 2016



C-AD ACTIVITY

MARCH 2016



INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM MARCH 2016

EBIS

Collector PS trip + vacuum problems

UPS

9b-UPS failed – trips many RHIC supplies

PS_RHIC

b2-dhx buffer card replaced

Rf_RHIC

Y&B Landau tripping / not ramping

Y storage cavities tripping

Rad Mon Pulls permit

3x

Controls Hd RHIC

WFG – wrong references – probably related to cfe-9b-ps1 rad related effects

ESHQ

IR6 smoke detector

Quench Detect

fecs corrupted 11b-qd1 & 9b-ps1

QLI

Debunched beam at dump – 56MHz MD

Voltage tap reads high

4 beam induced


Cryo_RHIC

Sector 11 rad induced communication loss with I/O crate

2/23/16/2 to 03/01/16/1

03/01/16/2 to 03/08/16/1

03/08/16/2 to 03/15/16/1



Run16 availability 81.5%

